

## Table of Contents

1	SUMMARY.....	5
2	FACTUAL INFORMATION.....	6
2.1	Photograph of the ship.....	6
2.2	Ship particulars.....	6
2.3	Voyage particulars.....	7
2.4	Marine casualty or incident information.....	7
2.5	Shore authority involvement and emergency response.....	8
3	COURSE OF THE ACCIDENT AND INVESTIGATION.....	9
3.1	Course of the accident.....	9
3.2	Investigation.....	10
3.2.1	Start of the investigation.....	10
3.2.2	PESORSA CUATRO.....	10
3.2.3	Surveys by the Ship Safety Division of BG Verkehr respective the classification society.....	14
3.2.4	Course of the voyage.....	15
3.2.5	Manning.....	16
3.2.6	Fishing process.....	16
3.2.7	Access to the observation deck.....	18
3.2.8	Observation deck.....	20
3.2.9	Weather.....	23
4	ANALYSIS.....	24
4.1	Course of the accident.....	24
4.2	Obligations of the company.....	24
4.3	Obligations of the employee.....	25
4.4	Surveys by the BG Verkehr and classification society.....	25
5	CONCLUSIONS.....	27
5.1	Obligations of the company.....	27
5.2	Inflatable lifejacket.....	27
5.3	Surveys by the Ship Safety Division of BG Verkehr.....	27
6	ACTIONS TAKEN.....	28
7	SAFETY RECOMMENDATIONS.....	30
7.1	Owner: Seamar GmbH.....	30
7.2	Owner: Seamar GmbH.....	30
7.3	Ship Safety Division of BG Verkehr.....	30
8	SOURCES.....	31