

TABLE OF CONTENTS

1. Introduction	1
1.1 Function of tuyeres in a blast furnace and consequences of their failure	1
1.2 Objects of the work	2
2. Literature review	3
2.1 Blast furnace operation	3
2.2 Basic chemical reactions of blast furnace ironmaking process	6
2.3 Circulation and accumulation of elements in blast furnace	8
2.4 Possible reasons for failure of blast furnace tuyeres	12
2.5 Ways for improving service life of blast furnace tuyeres	14
2.6 Chemical and physical properties of copper	15
2.7 Corrosion and its forms	18
2.8 Corrosion of copper and copper alloys	20
3. Failure mechanism of blast furnace tuyeres	24
3.1 Possible corrosion models for the failure mechanism	28
3.2 Model of chlorine cycle in blast furnace	33
3.3 Influence of process parameters on tuyeres failure	36
4. Experimental work	39
4.1 Investigation of the destruction of copper by pure thermal attack	39
4.1.1 Short-term attack of liquid pig iron on a water-cooled copper block	39
4.1.2 Effect of the heat produced by a plasma burner on a water-cooled copper block	41
4.1.3 Investigation of the possibility of welding between pig iron and cooled copper by heat from an oxygen-acetylene burner	42
4.1.4 Investigation of the possibility of welding between pig iron and non-cooled copper by heat from an oxygen-acetylene burner	43
4.1.5 Long-term attack of liquid pig iron on a non-cooled tuyere section	44
4.1.6 Metallographic examination of the tuyere section damaged by the stream of liquid pig iron	46

4.2	Examination of failed tuyeres	53
4.2.1	Visual inspection of failed tuyeres	53
4.2.2	Metallographic examination of the samples of failed tuyeres	55
4.2.2.1	Microstructure of the iron layer	57
4.2.2.2	Microstructure of the copper in the contact zone copper/iron	64
4.2.2.3	Elemental distribution maps of a failure site	69
4.3	Laboratory simulation of a blast furnace – Tammann furnace experiments	73
4.3.1	Corrosive effect of a coke-sinter mixture on a tuyere section in a Tammann furnace	76
4.3.2	Corrosion of a tuyere section under an increased chlorine content within the Tammann furnace	77
4.3.3	Transport of chlorine within the Tammann furnace	79
4.4	Corrosion experiments performed on the copper samples	82
4.4.1	Copper corrosion in aqueous solutions	82
4.4.1.1	Copper corrosion in aqueous solutions of HCl and H ₂ SO ₄	82
4.4.1.2	Metallographic examination of the copper samples after exposure to the acidic solutions	84
4.4.2	High-temperature corrosion of copper in salts	86
4.5	Influence of cementite on the dissolution behaviour of copper in HCl	89
4.5.1	Obtaining the pig iron with an increased cementite content	89
4.5.2	Dissolution behaviour of the copper-iron couples immersed in HCl solution	91
4.6	Tuyere materials with improved properties	98
4.6.1	Corrosion behaviour of the copper alloys in HCl solution	103
4.6.2	Microstructure of the Cu-10 wt. % Ti alloy before and after corrosion in HCl solution	108
4.6.3	Microstructure of the Cu-1 wt. % Zr alloy before and after corrosion in HCl solution	112
4.6.4	Microstructure of the Cu-1 wt. % Cr alloy before and after corrosion in HCl solution	115
5.	Conclusions	117
	Literature	120