

Table of Contents

	Page
Preface	XI
A Guide to this Book	XIII
1 Introduction	1
1.1 Quality and Quality Assurance	3
1.1.1 Quality as an Entrepreneurial Strategy	3
1.1.2 The Concept of Quality	4
1.1.3 Quality Differences and their Causes	7
1.1.4 Quality Assurance	11
1.2 Statistical Quality Assurance	14
1.2.1 Two Examples from Practice	14
1.2.2 Goals of Statistical Quality Assurance	16
1.2.3 Classification of Statistical Quality Assurance	17
1.3 Evolution of Quality Assurance	21
1.3.1 Historical Development of Quality Assurance	21
1.3.2 The Present Situation and Trends in Quality Assurance	27
1.3.3 Computer Aided Quality Assurance – A Module of Computer Integrated Manufacturing	34
2 Foundations of Statistical Quality Assurance	39
2.1 Distributions of Quality Characteristics	41
2.1.1 Measuring Quality Characteristics	41
2.1.2 Distributions of Qualitative Characteristics	43
2.1.3 Discrete Distributions	46
a) The Uniform Distribution and Basic Concepts of Statistical Distribution Theory ..	46
b) The Bernoulli Distribution	52
c) The Poisson Distribution	55
2.1.4 Continuous Distributions	58
a) Rectangular Distribution, Beta Distribution and Basic Concepts of Statistical Distribution Theory	58
b) Exponential, Gamma and other Lifetime Distributions	63
c) The Normal Distribution	68
d) Approximations with the Normal Distribution	76

2.2	Sampling and Sampling Distributions	81
2.2.1	Basic Concepts	81
a)	Quality Characteristics and Quality Standards	81
b)	Basic Terminology of Sampling Theory	82
c)	Realization of Random Samples	82
2.2.2	Sample Statistics and their Properties	85
a)	Common Sample Statistics	89
b)	Desirable Properties	93
2.2.3	Distributions of Sample Statistics	96
a)	The Normal Distribution as an Asymptotic Distribution of Sample Statistics	96
b)	The Hypergeometric and Negative Hypergeometric Distribution	98
c)	The Binomial and Negative Binomial Distribution	104
d)	The t Distribution	109
e)	The χ^2 Distribution	112
f)	The F Distribution	115
2.3	Fundamentals of Hypothesis Testing	119
2.3.1	Basic Ideas of Hypothesis Testing	119
a)	Errors in Hypothesis Tests	119
b)	Parameters Influencing the Error Probabilities	120
2.3.2	Design and Applications of Parameter Tests	125
a)	Steps of a Parameter Test	125
b)	Two Examples from Practice	128
c)	Power Function, Operating Characteristic Function and OC Percentiles	132
d)	Derivation of the Power Function for two Tests	135
e)	Slope and Elasticity	139
2.3.3	Sequential Tests	143
a)	The Likelihood Ratio Test (LR Test)	143
b)	Sequential LR Test for a Bernoulli Distributed Population	144
c)	Sequential LR Test for a Normally Distributed Population	147
2.3.4	Testing for Equality of Parameters for Normally Distributed Populations	149
3	Acceptance Sampling	151
3.1	Overview	153
3.1.1	Basic Concepts	153
3.1.2	Application of Sampling Plans in Practice	155
3.2	Acceptance Sampling for Attributes	158
3.2.1	Single-Sampling Plans	158
a)	Single-Sampling Plan Procedure and MOOD's Theorem	158
b)	The Hypergeometric OC Function	163

c)	The Binomial OC Function	170
d)	The Poisson OC Function	172
e)	Comparison of the three OC Functions	177
3.2.2	Measuring the Performance of Single-Sampling Plans	183
a)	OC Percentiles	183
b)	Average Outgoing Quality (AOQ and AOQL)	191
c)	Average Total Inspection and Average Fraction Inspected (ATI and AFI)	199
d)	Curtailed Inspection and Average Sample Number (ASN)	204
3.2.3	Designing Single-Sampling Plans with Specified Properties	209
a)	Specification of Consumer's and Producer's Risk	210
b)	Other Specifications	221
3.2.4	Double-Sampling Plans	221
a)	Double-Sampling Procedure	222
b)	OC Function	226
c)	Average Sample Number (ASN)	231
d)	Other Measures of Performance (AOQ, AOQL, ATI and AFI)	234
e)	Equivalent Single-Sampling and Double-Sampling Plans	237
3.2.5	Multiple-Sampling Plans	239
3.2.6	Sequential-Sampling Plans	242
a)	Sequential-Sampling Procedure	242
b)	OC Function and Average Sample Number (ASN)	248
3.2.7	Sampling Systems	254
a)	Construction of Sampling Systems and New Developments	254
b)	The ANSI/ASQC Z 1.4 (ISO 2859)	256
c)	Evaluation of Plans in the ISO 2859	265
d)	Dynamic Sampling Systems	268
e)	Further Sampling Systems	272
3.2.8	Special Topics	274
a)	Effects of Misclassification on the OC Function and other Performance Measures for Single-Sampling Plans	274
b)	Economic Acceptance Sampling	286
3.3	Acceptance Sampling by Variables	296
3.3.1	Relationship between Fraction Defective and Process Mean	296
3.3.2	Sampling Plans for a Single Specification Limit and Known Variance	304
a)	Procedure and Introduction of Appropriate Test Statistics	305
b)	OC Functions and Measures of Performance	309
c)	Designing Plans a for Specified Consumer's and Producer's Risk	314
3.3.3	Sampling Plans for a Single Specification Limit and Unknown Variance	318
a)	Introduction of Appropriate Test Statistics	318
b)	OC Functions and Designing Plans with Specified Consumer's and Producer's Risk	320

3.3.4	Sampling Plans with Double Specification Limits	324
3.3.5	Comparison of Acceptance Sampling by Variables and by Attributes	325
3.3.6	Sampling Systems by Variables	326
4	Statistical Process Control	329
4.1	Continuous Sampling Plans	331
4.1.1	The CSP-1	332
a)	Description of a CSP-1	332
b)	Measuring the CSP-1 Performance	335
c)	Designing a CSP-1 with Specified Properties	344
d)	Average Outgoing Quality Limit under Altered Model Assumptions	348
4.1.2	Modifications and Extensions of the CSP-1	351
a)	The CSP-2 and CSP-3	351
b)	Multilevel Continuous Sampling Plans	354
c)	Block Continuous Plans	355
4.2	Control Charts	359
4.2.1	Control Chart Principles	359
a)	Basic Idea of a Control Chart	359
b)	Designing a Control Chart	362
c)	Benefits from Using Control Charts	365
4.2.2	Types of Control Charts	366
4.2.3	Hypothesis Testing and Control Charts	369
4.3	SHEWHART Control Charts for Attributes	372
4.3.1	Control Charts for the Number of Nonconformities	372
a)	Onesided \bar{x} Charts for Nonconformities per Product Unit	373
b)	Twosided \bar{x} Charts for Nonconformities per Product Unit	380
c)	u Charts for Nonconformities per Physical Unit	382
d)	Randomized Tests	383
4.3.2	Control Charts for the Number or the Fraction of Nonconforming Units	384
a)	x Charts for the Number of Nonconforming Units	385
b)	p Charts for the Fraction of Nonconforming Units	388
4.3.3	Charts for Multiple Nonconformities and the PARETO Diagram	389
4.4	SHEWHART Control Charts for Variables	392
4.4.1	Evaluation of a Prerun	393
a)	Aggregating the Prerun Data	393
b)	Testing for Disturbances in the Prerun Data	395
c)	Estimating the Process Level	399
d)	Estimating the Process Spread	400

4.4.2	Control Charts for Monitoring the Process Level	405
a)	Introductory Remarks	405
b)	Mean Charts (\bar{x} charts)	407
c)	Median Charts (\tilde{x} charts)	411
d)	Extreme Value Charts (x charts)	413
e)	Comparison of Mean, Median and Extreme Value Charts	416
f)	Single Observation Charts (x charts)	417
4.4.3	Control Charts for Monitoring the Process Spread	419
a)	Introductory Remarks	419
b)	Standard Deviation Charts (s charts)	421
c)	Range Charts (r charts)	425
d)	Extreme Value Charts (x charts)	427
e)	Comparison of Standard Deviation, Range and Extreme Value Charts	428
4.4.4	Control Charts for Simultaneously Monitoring Process Level and Process Spread	429
4.4.5	Special Topics	434
a)	Effects of Measurement Errors on the Performance of SHEWHART Control Charts	434
b)	Economic Design of SHEWHART Control Charts	441
4.5	Modified SHEWHART Charts for Variables	451
4.5.1	Process Capability Studies	451
4.5.2	Control Charts for Monitoring the Process Level	457
a)	Introductory Remarks	457
b)	Mean Charts	462
c)	Median Charts	467
d)	Extreme Value Charts	468
e)	Comparison of Mean, Median and Extreme Value Charts	471
4.6	Control Charts with Memory	474
4.6.1	Classification of Control Charts with Respect to their Memory	474
4.6.2	CUSUM-Mean Charts	478
a)	Introductory Remarks	478
b)	Sensitivity of the CUSUM Chart towards Shifts in the Process Level and Procedures for Evaluation	480
c)	Average Run Length (ARL)	491
d)	Test-theoretical Background of CUSUM Charts	492
e)	Cusum- \bar{x} Chart Design and Equivalence of V Mask and Tabular CUSUM Form	495
4.6.3	EWMA-Mean Charts	500
a)	Introductory Remarks	500
b)	Average Run Length (ARL) and Design of EWMA- \bar{x} Charts	502
c)	Sensitivity of the EWMA Chart towards Shifts in the Process Level	504

5	Statistical Tables	507
5.1	Distribution Functions	509
5.1.1	Standard Normal Distribution	509
5.1.2	Hypergeometric Distribution	511
5.1.3	Binomial Distribution	515
5.1.4	Poisson Distribution	519
5.2	Percentile Functions	523
5.2.1	Percentiles of the Standard Normal Distribution	523
5.2.2	Percentiles of the <i>t</i> Distribution	525
5.2.3	Percentiles of the <i>F</i> Distribution	528
5.2.4	Percentiles of the χ^2 Distribution	532
5.2.5	Percentiles of a Special Gamma Distribution	534
5.3	Special Tables	536
5.3.1	Special Factors	536
5.3.2	Percentiles of the Standardized Sample Range	538
6	Solutions to Exercises	539
6.1	Solutions for Chapter 2	541
6.2	Solutions for Chapter 3	567
6.3	Solutions for Chapter 4	601
7	Index Lists	617
7.1	Bibliography	619
7.1.1	Annotated Reference List of Selected Journals, Textbooks and Reference Books	619
7.1.2	Complete Bibliography	624
7.2	Abbreviations, Symbols and Index Registers	641
7.2.1	Abbreviations and Mathematical Symbols	641
7.2.2	Author Index	644
7.2.3	Subject Index	647