

Contents

Preface	V
About the Authors	VII
1 Troubleshooting Methodology	1
1.1 Troubleshooting	1
1.2 What Makes an Effective Troubleshooter?	1
1.3 What Makes an Ineffective Troubleshooter?	3
1.4 Troubleshooting Methodology	3
1.4.1 STOP: Systematically	4
1.4.2 STOP: Think	6
1.4.3 STOP: Observe	7
1.4.4 STOP: Proceed	10
1.4.5 STOP: Troubleshooting Cycle	12
1.4.6 Hard Fix versus Processing around Problem	13
1.4.7 Troubleshooting Tools	13
1.4.8 Troubleshooting Methodology Summary	18
2 Troubleshooting Tool Kit	21
2.1 Lockout/Tagout	21
2.2 Hand Tools	21
2.3 Pyrometer	22
2.4 Spotting Blue	22
2.5 Measurement Tools	22
2.6 Multimeter	22
2.7 Process Monitoring Equipment	23
2.8 Moisture Analyzer	23

2.9	Dew Point Meter	23
2.10	Flashlight	24
2.11	Microscope/Magnifying Glass	24
2.12	Silly Putty	24
2.13	Inspection Mirror	24
2.14	Thermal Imaging Camera	25
2.15	Aluminum Tape	25
2.16	Dial Indicator	25
2.17	Purging Compound	25
2.18	Grinder/Stones	26
2.19	Camera	26
2.20	Material Data	26
2.21	Scale	26
2.22	Flow Meter	27
2.23	Mold Cleaning Supplies	27
2.24	Miscellaneous Supplies	27
3	Decoupled® or Scientific Molding	29
4	Gating Details	33
4.1	Gating	33
4.2	Gate Size, Shape, and Taper	35
4.3	Mental Picture Volume versus Pressure	40
5	Mold Hydraulics	41
5.1	Hydraulic Uses	41
5.2	Set and Pull Pressure	41
5.3	Cylinder Sizing	42
5.4	Hydraulic Cores or Slides	44
5.5	Multiple Sequences	44
5.6	Mounting	45
5.7	Switches	45

6	Mold Texture and Polish	47
6.1	Mold Texture	47
6.2	Mold Polish	50
7	Venting	53
7.1	Venting Basics	53
7.2	Alternate Venting	58
7.3	Venting Conclusion	60
8	Machine Performance	61
8.1	Load Sensitivity	63
8.2	Dynamic Check Valve Study	64
8.3	Velocity Linearity	65
8.4	10-Cycle Overlay	68
8.5	Cycle Variation	70
8.6	Velocity to Pressure Transfer	72
	8.6.1 Machine Control	75
8.7	Machine Documentation	78
9	Drying	81
9.1	Introduction	81
9.2	Keys to Drying	81
	9.2.1 Temperature	83
	9.2.2 Dry Air	83
	9.2.3 Air Flow	85
	9.2.4 Time	85
9.3	Moisture Analysis	86
9.4	Material Handling	88
9.5	Material Concerns	90
10	Purging	91
10.1	Purging Impact	91
10.2	Purging Method Example	92
10.3	Purging Compounds	93

11	Hot Runners	95
11.1	Hot Runner Advantages	95
11.2	Heaters and Thermocouples	95
11.3	Hang Up Areas	96
11.4	Hot Drop Tips	96
11.5	Drooling, Stringing, and Sprue Sticking	97
11.6	Freeze Off	97
11.7	Orifice Size	97
11.8	Leakage	98
11.9	Zones and Wiring	99
11.10	Hot Runner Troubleshooting	99
12	Cavity Balance	101
12.1	Flow Length	103
12.2	Flow Diameter	103
12.3	Shear	103
12.4	Cooling	105
12.5	Venting	106
12.6	Clamp Pressure	106
12.7	Cavity Fill Balance Study	107
12.8	Artificial Balance	108
12.8.1	Family Molds	109
13	Cavity Instrumentation	111
13.1	Cavity Pressure Technology	111
13.2	Cavity Thermocouples	118
13.3	Process Documentation	121
13.4	Process Control	122
13.5	Additional Monitoring Options	123
14	Mold Cooling	125
14.1	Mold Cooling Importance	125
14.2	Water Flow	126
14.3	Documentation	127

14.4	Tooling Techniques	128
14.5	Other Cooling Concerns	130
15	Black or Brown Specks	131
15.1	Description	131
15.2	Black Specks Troubleshooting Chart	132
15.3	Black Specks Troubleshooting	132
15.3.1	Black Specks Troubleshooting Molding Process Issues	132
15.3.2	Black Specks Troubleshooting Mold Issues	133
15.3.3	Black Specks Troubleshooting Machine Issues	135
15.3.4	Black Specks Troubleshooting Material Issues	137
16	Blush	141
16.1	Description	141
16.2	Blush Troubleshooting Chart	142
16.3	Blush Troubleshooting	142
16.3.1	Blush Troubleshooting Molding Process Issues	142
16.3.2	Blush Troubleshooting Tooling Issues	145
16.3.3	Blush Troubleshooting Machine Issues	148
16.3.4	Blush Troubleshooting Material Issues	149
17	Brown Streaks	151
17.1	Description	151
17.2	Brown Streak Troubleshooting Chart	152
17.3	Brown Streak Troubleshooting	152
17.3.1	Brown Streak Troubleshooting Molding Process Issues	152
17.3.2	Brown Streak Troubleshooting Mold Issues	156
17.3.3	Brown Streak Troubleshooting Machine Issues	159
17.3.4	Brown Streak Troubleshooting Material Issues	162
18	Bubbles	165
18.1	Description	165
18.2	Bubbles Troubleshooting Chart	166
18.3	Bubbles Troubleshooting	166
18.3.1	Bubbles Troubleshooting Molding Process Issues	167
18.3.2	Bubbles Troubleshooting Mold Issues	168
18.3.3	Bubbles Troubleshooting Machine Issues	170
18.3.4	Bubbles Troubleshooting Material Issues	171

19	Buildup	173
19.1	Description	173
19.2	Buildup Troubleshooting Chart	174
19.3	Buildup Troubleshooting	174
19.3.1	Buildup Troubleshooting Molding Process Issues	174
19.3.2	Buildup Troubleshooting Mold Issues	175
19.3.3	Buildup Troubleshooting Machine Issues	177
19.3.4	Buildup Troubleshooting Material Issues	177
20	Burns	181
20.1	Description	181
20.2	Burns Troubleshooting Chart	182
20.3	Burns Troubleshooting	182
20.3.1	Burns Troubleshooting Molding Process Issues	182
20.3.2	Burns Troubleshooting Mold Issues	184
20.3.3	Burns Troubleshooting Machine Issues	186
20.3.4	Burns Troubleshooting Material Issues	189
21	Cloudiness	191
21.1	Description	191
21.2	Cloudiness Troubleshooting Chart	192
21.3	Cloudiness Troubleshooting	192
21.3.1	Cloudiness Troubleshooting Molding Process Issues	192
21.3.2	Cloudiness Troubleshooting Mold Issues	194
21.3.3	Cloudiness Troubleshooting Machine Issues	195
21.3.4	Cloudiness Troubleshooting Material Issues	196
22	Color Swirls	199
22.1	Description	199
22.2	Color Swirls Troubleshooting Chart	200
22.3	Color Swirls Troubleshooting	200
22.3.1	Color Swirls Troubleshooting Molding Process Issues	200
22.3.2	Color Swirls Troubleshooting Mold Issues	202
22.3.3	Color Swirls Troubleshooting Machine Issues	202
22.3.4	Color Swirls Troubleshooting Material Issues	204
23	Contamination	209
23.1	Description	209

23.2	Contamination Troubleshooting Chart	210
23.3	Contamination Troubleshooting	210
23.3.1	Contamination Troubleshooting Molding Process Issues	210
23.3.2	Contamination Troubleshooting Mold Issues	212
23.3.3	Contamination Troubleshooting Machine Issues	215
23.3.4	Contamination Troubleshooting Material Issues	217
24	Cracking	223
24.1	Description	223
24.2	Cracking Troubleshooting Chart	224
24.3	Cracking Troubleshooting	224
24.3.1	Cracking Troubleshooting Molding Process Issues	224
24.3.2	Cracking Troubleshooting Mold Issues	228
24.3.3	Cracking Troubleshooting Machine Issues	229
24.3.4	Cracking Troubleshooting Material Issues	230
25	Delamination	233
25.1	Description	233
25.2	Delamination Troubleshooting Chart	234
25.3	Delamination Troubleshooting	234
25.3.1	Delamination Troubleshooting Molding Process Issues	234
25.3.2	Delamination Troubleshooting Mold Issues	235
25.3.3	Delamination Troubleshooting Machine Issues	236
25.3.4	Delamination Troubleshooting Material Issues	237
26	Dimensions	239
26.1	Description	239
26.2	Dimensions Troubleshooting Chart	239
26.3	Dimensions Troubleshooting	240
26.3.1	Dimensions Troubleshooting Molding Process Issues	240
26.3.2	Dimensions Troubleshooting Mold Issues	245
26.3.3	Dimensions Troubleshooting Machine Issues	247
26.3.4	Dimensions Troubleshooting Material Issues	251
27	Excessive Cycle Time	255
27.1	Description	255
27.2	Excessive Cycle Time Troubleshooting Chart	255
27.3	Excessive Cycle Time Troubleshooting	256

27.3.1	Excessive Cycle Time Troubleshooting Molding Process Issues	256
27.3.2	Excessive Cycle Time Troubleshooting Mold Issues	259
27.3.3	Excessive Cycle Time Troubleshooting Machine Issues	262
27.3.4	Excessive Cycle Time Troubleshooting Material Issues	263
28	High Fill Pressure	265
28.1	Description	265
28.2	High Fill Pressure Troubleshooting Chart	265
28.3	High Fill Pressure Troubleshooting	266
28.3.1	High Fill Pressure Troubleshooting Molding Process Issues ..	266
28.3.2	High Fill Pressure Troubleshooting Mold Issues	267
28.3.3	High Fill Pressure Troubleshooting Machine Issues	269
28.3.4	High Fill Pressure Troubleshooting Material Issues	274
29	Flaking	277
29.1	Description	277
29.2	Flaking Troubleshooting Chart	278
29.3	Flaking Troubleshooting	278
29.3.1	Flaking Troubleshooting Molding Process Issues	278
29.3.2	Flaking Troubleshooting Mold Issues	278
29.3.3	Flaking Troubleshooting Machine Issues	280
29.3.4	Flaking Troubleshooting Material Issues	280
30	Flash	281
30.1	Description	281
30.2	Flash Troubleshooting Chart	282
30.3	Flash Troubleshooting	282
30.3.1	Flash Troubleshooting Molding Process Issues	283
30.3.2	Flash Troubleshooting Mold Issues	287
30.3.3	Flash Troubleshooting Machine Issues	292
30.3.4	Flash Troubleshooting Material Issues	296
31	Flow Lines	299
31.1	Description	299
31.2	Flow Lines Troubleshooting Chart	299
31.3	Flow Lines Troubleshooting	300
31.3.1	Flow Lines Troubleshooting Molding Process Issues	300

31.3.2	Flow Lines Troubleshooting Mold Issues	302
31.3.3	Flow Lines Troubleshooting Machine Issues	304
31.3.4	Flow Lines Troubleshooting Material Issues	306
32	Glass Fibers on Surface	309
32.1	Description	309
32.2	Glass Fibers on Surface Troubleshooting Chart	310
32.3	Glass Fibers on Surface Troubleshooting	310
32.3.1	Glass Fibers on Surface Troubleshooting Molding Process Issues	310
32.3.2	Glass Fibers on Surface Troubleshooting Mold Issues	312
32.3.3	Glass Fibers on Surface Troubleshooting Machine Issues	314
32.3.4	Glass Fibers on Surface Troubleshooting Material Issues	315
33	Gloss Variation	319
33.1	Description	319
33.2	Gloss Variation Troubleshooting Chart	320
33.3	Gloss Variation Troubleshooting	320
33.3.1	Gloss Variation Troubleshooting Molding Process Issues	320
33.3.2	Gloss Variation Troubleshooting Mold Issues	324
33.3.3	Gloss Variation Troubleshooting Machine Issues	327
33.3.4	Gloss Variation Troubleshooting Material Issues	327
34	Jetting	331
34.1	Description	331
34.2	Jetting Troubleshooting Chart	332
34.3	Jetting Troubleshooting	332
34.3.1	Jetting Troubleshooting Molding Process Issues	333
34.3.2	Jetting Troubleshooting Mold Issues	334
34.3.3	Jetting Troubleshooting Machine Issues	336
34.3.4	Jetting Troubleshooting Material Issues	336
35	Part Sticking on Cover	337
35.1	Description	337
35.2	Part Sticking on Cover Troubleshooting Chart	337
35.3	Part Sticking on Cover Troubleshooting	338
35.3.1	Part Sticking on Cover Troubleshooting Molding Process Issues	338

35.3.2	Part Sticking on Cover Troubleshooting Mold Issues	339
35.3.3	Part Sticking on Cover Troubleshooting Machine Issues	342
35.3.4	Part Sticking on Cover Troubleshooting Material Issues	343
36	Part Sticking on Ejector	345
36.1	Description	345
36.2	Part Sticking on Ejector Troubleshooting Chart	346
36.3	Part Sticking on Ejector Troubleshooting	346
36.3.1	Part Sticking on Ejector Molding Process Issues	346
36.3.2	Part Sticking on Ejector Troubleshooting Mold Issues	349
36.3.3	Part Sticking on Ejector Troubleshooting Machine Issues	351
36.3.4	Part Sticking on Ejector Troubleshooting Material Issues	352
37	Pin Push	355
37.1	Description	355
37.2	Pin Push Troubleshooting Chart	356
37.3	Pin Push Troubleshooting	356
37.3.1	Pin Push Troubleshooting Mold Process Issues	356
37.3.2	Pin Push Troubleshooting Mold Issues	358
37.3.3	Pin Push Troubleshooting Machine Issues	360
37.3.4	Pin Push Troubleshooting Material Issues	361
38	Read-through	363
38.1	Description	363
38.2	Read-through Troubleshooting Chart	364
38.3	Read-through Troubleshooting	364
38.3.1	Read-through Troubleshooting Molding Process Issues	364
38.3.2	Read-through Troubleshooting Mold Issues	365
38.3.3	Read-through Troubleshooting Machine Issues	367
38.3.4	Read-through Troubleshooting Material Issues	367
39	Scuffs and Scratches	369
39.1	Description	369
39.2	Scuffs and Scratches Troubleshooting Chart	370
39.3	Scuffs and Scratches Troubleshooting	370
39.3.1	Scuffs and Scratches Troubleshooting Molding Process Issues	370
39.3.2	Scuffs and Scratches Troubleshooting Mold Issues	373

39.3.3	Scuffs and Scratches Troubleshooting Machine Issues	375
39.3.4	Scuffs and Scratches Troubleshooting Material Issues	375
40	Short Shot	377
40.1	Description	377
40.2	Short Shot Troubleshooting Chart	378
40.3	Short Shot Troubleshooting	378
40.3.1	Short Shot Troubleshooting Molding Process Issues	378
40.3.2	Short Shot Troubleshooting Mold Issues	385
40.3.3	Short Shot Troubleshooting Machine Issues	389
40.3.4	Short Shot Troubleshooting Material Issues	393
41	Sink	397
41.1	Description	397
41.2	Sink Troubleshooting Chart	398
41.3	Sink Troubleshooting	398
41.3.1	Sink Troubleshooting Molding Process Issues	398
41.3.2	Sink Troubleshooting Mold Issues	404
41.3.3	Sink Troubleshooting Machine Issues	408
41.3.4	Sink Troubleshooting Material Issues	411
42	Splay	413
42.1	Description	413
42.2	Splay Troubleshooting Chart	414
42.3	Splay Troubleshooting	414
42.3.1	Splay Troubleshooting Molding Process Related Issues	415
42.3.2	Splay Troubleshooting Mold Issues	420
42.3.3	Machine Issues	425
42.3.4	Material Issues	427
43	Sprue Sticking	431
43.1	Description	431
43.2	Sprue Sticking Troubleshooting Chart	432
43.3	Sprue Sticking Troubleshooting	432
43.3.1	Sprue Sticking Troubleshooting Molding Process Issues	432
43.3.2	Sprue Sticking Troubleshooting Mold Issues	435
43.3.3	Sprue Sticking Troubleshooting Machine Issues	439
43.3.4	Sprue Sticking Troubleshooting Material Issues	441

44	Stringers	443
44.1	Description	443
44.2	Stringers Troubleshooting Chart	444
44.3	Stringers Troubleshooting	444
44.3.1	Stringers Troubleshooting Molding Process Issues	444
44.3.2	Stringers Troubleshooting Mold Issues	446
44.3.3	Stringers Troubleshooting Machine Issues	448
44.3.4	Stringers Troubleshooting Material Issues	450
45	Voids	451
45.1	Description	451
45.2	Voids Troubleshooting Chart	452
45.3	Voids Troubleshooting	452
45.3.1	Voids Troubleshooting Molding Process Issues	452
45.3.2	Voids Troubleshooting Mold Issues	454
45.3.3	Voids Troubleshooting Machine Issues	456
45.3.4	Voids Troubleshooting Material Issues	456
46	Warp	457
46.1	Description	457
46.2	Warp Troubleshooting Chart	457
46.3	Warp Troubleshooting	458
46.3.1	Warp Troubleshooting Molding Process Issues	459
46.3.2	Warp Troubleshooting Mold Issues	465
46.3.3	Warp Troubleshooting Machine Issues	467
46.3.4	Warp Troubleshooting Material Issues	468
47	Weld Lines	471
47.1	Description	471
47.2	Weld Lines Troubleshooting Chart	472
47.3	Weld Lines Troubleshooting	472
47.3.1	Weld Lines Troubleshooting Molding Process Issues	473
47.3.2	Weld Lines Troubleshooting Mold Issues	475
47.3.3	Weld Lines Troubleshooting Machine Issues	477
47.3.4	Weld Lines Troubleshooting Material Issues	478
	Index	481