

Table of content

1	Introduction.....	1
2	Titanium, Consume and Price	3
2.1	Titanium Components Cost	4
2.2	Titanium Economics	6
2.2.1	Titanium Powder Market.....	8
3	Powder Metallurgy and Powder Production of Titanium.....	10
3.1	Methods of Powder Metallurgy	11
3.1.1	Metal Powder Injection Molding.....	11
3.1.2	Net Shape Techniques	12
3.2	Variables in Powder Metallurgy	17
3.2.1	Powder Characteristics.....	17
3.2.2	Powder Chemistry	19
3.3	Titanium Powder Classification	20
3.4	Industrial Powder Production Processes	20
3.4.1	Historical Overview.....	21
3.4.2	Chemical Reduction	22
3.4.3	Plasma Rotating Electrode Process (PREP).....	24
3.4.4	Hydriding-Dehydriding (HDH) Process	26
3.4.5	ADMA Process	28
3.4.6	Armstrong Process/ITP	29
3.5	Pre-commercial Powder Production Processes	31
3.5.1	TiRo™ Process	31
3.5.2	MER Process	33
3.5.3	FCC Process	34
3.5.4	EMR/MSE Process.....	35
3.5.5	PPR Process	37
3.6	Powder Production	37
3.7	Comparison of Powder Production Processes	42
3.8	Proposed Process for Ti-Powder Production.....	44
4	Process Development	45
4.1	Historic Overview of Magnesiothermic Reduction	45
4.2	Thermochemical Background of Magnesiothermic Reduction	48
4.2.1	Modelling of the Ternary Diagram Ti-Mg-O	49
4.2.2	Reaction Progress.....	51
4.2.3	Stable Phases after Cooling	56
4.2.4	Process Temperature	59

4.3	Experimental Set up	61
4.3.1	Reactor I	61
4.3.2	Reactor II	64
4.3.3	Reactor III	67
4.4	Products Characterisation	69
4.4.1	Strongly Reduced Product.....	70
4.4.2	Weakly Reduced Product	77
4.4.3	Other Products	78
4.4.4	Distribution of Reaction Products	80
5	Impact of Parameter Variation on Magnesiothermic Reduction	86
5.1	Influence of the Molar Composition Ratio (φ)	86
5.2	Set Temperature and Holding Reaction Time.....	87
5.3	The Shape of Magnesium Used for Reduction	88
5.4	Particle Size and Form of the Titanium Oxide	90
6	The Mechanism-Pathway of the Magnesiothermic Reduction	92
6.1	Starting of Reaction	92
6.2	Magnesium Partial Pressure.....	93
6.3	Phase Formation	95
6.4	The Thermochemical Staircase of the Magnesiothermic Reduction	96
6.4.1	Stage I: Reduction of TiO_2 to Ti_2O_3 and Mg_2TiO_4	98
6.4.2	Stage II: Reduction from Mg_2TiO_4 to $Ti[O]_8$	98
6.4.3	Reactants in Contact with each other and High Molar Ratio	99
6.4.4	Reactants in Contact with each other and Low Molar Ratio	100
6.4.5	Reactants Separate each other	101
6.5	Reactor Design, the Key to a High Efficiency Reaction	101
6.5.1	Evaporation System.....	103
6.5.2	Reduction Zones	103
6.5.3	Collector Vessel.....	103
7	Leaching of the Magnesiothermic Reduction Products	105
7.1	Experimental.....	105
7.2	Results and Analysis	107
8	The Obtained Powder.....	110
8.1	Degree of Reduction.....	110

8.2	Morphology of Powder from RI (Argon Protective Reactor).....	110
8.3	Morphology of Powder from RII (Sealed Reactor)....	111
8.4	Morphology of Powder from RIII (Two Compartment Reactor).....	112
8.4.1	Equiaxed Particles.....	112
8.4.2	Spherical and Semi-spherical Particles	113
8.4.3	Continuous Matrix Structure	114
8.5	Morphology Conclusions	115
8.5.1	Reaction Steps of Magnesiothermic Reaction.....	116
9	Conclusions and Outlook.....	118
10	Bibliography and Webography	122
11	Annexes	131
11.1	Size Distribution of the TiO ₂ Pigment	131
11.2	Drawing of Reactors	132
11.2.1	Drawing of Reactor II.....	132
11.2.2	Drawing of Reactor III.....	134
11.3	Experimental Planning and Results for Reactor I	139
11.3.1	First Experimental Series RI (Argon Protective Reactor).....	139
11.3.2	Second Experimental Series RI.....	139
11.3.3	Third Experimental Series RI.....	141
11.4	Experimental and Results Reactor II(Sealed Reactor).....	141
11.4.1	First Experimental Series RII.....	141
11.4.2	Second Experimental Series RII.....	142
11.5	Experimental Planning and Results for Reactor III (Two Compartment Reactor).....	143
11.5.1	First Experimental Series RIII.....	143
11.5.2	Second Experimental Series RIII.....	144
11.5.3	Third Experimental Series RIII.....	144
11.5.4	Leaching of the Weakly Reduced Product.....	145
11.5.5	Morphology of Weakly Reduced Product from RIII-Ni ₄	147