

# Table of Contents

Foreword by the Author .....	3
Bibliography .....	9
Introduction .....	11
1 Basic Term: Wire Drawing .....	12
2 Operating Principle of Wire Drawing Systems .....	13
2.1 Continuous Wire Drawing .....	13
2.2 Slip and Non-Slip Wire Drawing .....	14
2.2.1 Non-Slip Wire Drawing .....	14
2.2.2 Slip Drawing .....	15
2.2.3 Slip .....	17
2.3 Multiwire Drawing and Quick-Change Systems .....	20
2.4 Recrystallisation Annealing .....	23
2.4.1 Stationary Annealer (Batch Annealer) .....	24
2.4.2 Continuous Resistance Annealer .....	24
2.4.3 Induction Annealer .....	28
2.5 Take-Up and Pay-Off of Single Wires and Multiwire Bundles .....	29
2.5.1 Dynamic Winding .....	30
2.5.1.1 Dynamic Winding .....	30
2.5.1.2 Dynamic Unwinding .....	31
2.5.2 Static Winding .....	31
2.5.2.1 Static Winding with Spools .....	31
2.5.2.1.1 Static Winding on Spools .....	32
2.5.2.1.2 Static Unwinding from Spools .....	33
2.5.2.2 Static Winding and Unwinding with Barrels .....	34
2.5.3 Single Spooler, Automatic Spooler, Double Spooler, Conveyor System ...	35
3 Wire Drawing Lines .....	37
3.1 Rod Breakdown Line .....	38
3.1.1 Wire Coil Pay-off for Rod Breakdown Lines .....	39
3.1.2 Rod Breakdown Line .....	40
3.1.3 Continuous Resistance Annealer for Rod Breakdown Lines .....	43
3.1.4 Wind-up Systems for Rod Breakdown Lines .....	44
3.2 Intermediate, Fine and Super Fine Wire; Multiwire Drawing Lines .....	46
3.2.1 Pay-off Systems .....	46
3.2.2 Multiwire Drawing Lines for the Diameter Range 1.4...0.05 mm .....	47
3.2.3 Pay-off Systems for the Diameter Range 1.4...0.05 mm .....	51
3.2.4 Redraw Wire .....	52
3.3 Inline Drawing Line .....	53
3.4 Auxiliary Units for Drawing Lines and Annealers .....	55
3.4.1 Supply Systems for Cooling Lubricants .....	55
3.4.2 Cleaning Systems for Cooling Lubricants .....	57
3.4.3 Compact Band Filter .....	58
3.4.4 Inert Gas Atmosphere in the Annealer .....	59
3.4.5 Wire Pointing Machines .....	62
3.4.5.1 Wire Pointing with Rollers .....	62

3.4.5.2 Wire Pointing by Heating.....	64
3.4.6 Welding Machines for Wire .....	65
3.4.6.1 Butt Welding.....	65
3.4.6.2 Cold Pressure Welding .....	66
3.4.6.3 Summary of the Pressure Welding Processes.....	68
3.4.7 Measuring Instruments for Quality Control of Wires.....	69
3.4.7.1 Measuring the Wire Diameter.....	69
3.4.7.2 Measuring the Electrical Resistance .....	70
3.4.7.3 Measuring the Elongation at Break .....	71
3.4.7.4 Measuring the Tension on the Running Wire .....	71
3.4.7.5 Measuring the Layer Thickness of Metallic Coatings on Wires .....	72
3.4.7.6 Optical Evaluation of Wire Surfaces and Drawing Dies.....	73
3.4.8 Measuring Devices for Troubleshooting in Wire Drawing Lines .....	74
4 Wire-Contacting Parts in the Drawing Line and Annealer.....	76
4.1 Drawing Cones, Drawing Capstans and Guide Pulleys.....	77
4.1.1 Drawing Cones and Drawing Capstans .....	77
4.1.2 Guide Pulleys and Deflection Rollers .....	80
4.2 Drawing Dies .....	81
4.2.1 Diamond Drawing Dies .....	82
4.2.2 Drawing Dies made from Polycrystalline Diamond (PCD).....	84
4.2.3 Synthetic Monocrystals .....	87
4.2.4 Die Case .....	87
4.2.5 Manufacturing the Drawing Die Bores.....	88
4.2.6 Drawing Die Geometry.....	88
4.2.7 Wear and Damage to Drawing Dies.....	94
4.2.7.1 Drawing Die Service Life .....	94
4.2.7.2 Damage to Drawing Dies .....	95
4.2.8 Inspection and Management of Drawing Dies.....	97
4.2.9 Calculation and Design of Drawing Die Sets.....	99
4.2.9.1 Single and Multi-stage Drawing.....	99
4.2.9.2 Drawing Die Sets based on Elongation.....	104
4.2.9.2.1 Wire Elongation (Conventional Method).....	104
4.2.9.2.2 Method of Half the Standard Tolerance .....	104
4.2.9.2.3 REDIES Matrix Method .....	105
4.2.10 Effect of Incorrect Drawing Die Gradation on the Drawing Process .....	107
4.3 Contact-Transmitting Elements in the Annealer .....	110
4.4 Wire Drying Nozzles in the Annealer.....	112
4.5 Wire Guiding Routes in the Wire Drawing System .....	114
5 Copper.....	116
5.1 From Copper Ore to Wire Rod .....	116
5.1.1 Copper ore .....	116
5.1.2 From Copper Ore to Pure Copper.....	117
5.1.3 Continuous Cast and Rolled Rod .....	118
5.1.3.1 Southwire Process .....	118
5.1.3.2 Contirod® Process .....	119
5.1.3.3 Properzi® Process .....	119
5.1.4 Other Methods for Rod or Cast Wire Production.....	119
5.1.4.1 Dipforming Process.....	119

5.1.4.2 Upcasting .....	120
5.1.5 Delivery Bundles of Wire Rod .....	120
5.1.6 Quality Assessment of Wire Rod.....	121
5.2 Mechanical and Electrical Characteristics of Copper .....	126
5.2.1 Influences of Forming on the Characteristics of Copper .....	126
5.2.2 Stretching and Forming of Copper Wires .....	127
5.2.3 Recrystallization of Copper .....	128
5.2.4 Influence of Impurities on the Qualities of Copper.....	131
5.2.5 Creep Rupture Strength of Hard Copper Wire .....	131
5.3 Wire Breakage in Copper Wire Production.....	133
5.3.1 Tensile Break .....	133
5.3.2 Inclusion Break.....	134
5.3.3 Cup and Cone Break.....	136
5.3.4 Wire Break with Surface Damage in the Form of Crow's Feet .....	137
5.3.5 Accumulated Copper in the Reduction Cone .....	139
5.3.6 Shear Break .....	140
5.3.7 Split-End Break .....	141
5.3.8 Fish-Mouth Break.....	141
5.3.9 Break in the Annealer.....	143
5.3.10 Wire Break Position and its Interpretation .....	143
5.3.11 Final Analysis of Wire Breaks.....	145
6 Disturbances during Drawing of Copper Wires.....	146
6.1 Possible Faults during Wire Drawing.....	146
6.1.1 Wire Breaks.....	147
6.1.2 Poor Wire Surface.....	147
6.1.3 Dimensional Deviations.....	147
6.1.4 High Tool Wear .....	148
6.2 Final Considerations on the Subject of Problems during Drawing.....	149
7 Cooling Lubricants.....	152
7.1 Water-Miscible Cooling Lubricant for Copper Wire Drawing.....	152
7.2 Handling of Water-Miscible Cooling Lubricants during Use.....	164
7.2.1 Work Needed When Changing the Cooling Lubricant.....	164
7.2.2 Water .....	165
7.2.3 Preparing Fresh Cooling Lubricant.....	166
7.2.4 Cooling Lubricant Maintenance / Measuring Methods .....	166
7.2.5 Appearance.....	167
7.2.6 Concentration.....	167
7.2.7 pH Value .....	167
7.2.8 Electrical Conductivity .....	168
7.2.9 Bacteria / Fungi / Yeast.....	168
7.2.10 Dissolved Copper .....	169
7.2.11 Nitrite.....	169
7.3 Final Considerations regarding Cooling Lubricants .....	169
8 Formulas and Equations regarding the Wire .....	170
8.1 Weight - Diameter - Cross-Sectional Area - Length .....	170
8.2 Electrical Resistance – Cross-Sectional Area .....	172
8.3 Calculation of Production Quantities of Wire .....	174

8.4 Calculation of Winding Length.....	175
8.5 Calculations of Metallic Coatings on Copper Wires.....	176
8.6 Change of Coating Thickness when Drawing Coated Wire.....	180
8.7 American Standard for Wire Dimensions AWG.....	181
8.7.1 Wires.....	181
8.7.1.1 Conversion from AWG No. to Wire Diameter in mm .....	182
8.7.1.2 Conversion from Wire Diameter in mm into AWG No. ....	182
8.7.2 Stranded Wire .....	183
8.7.2.1 Conversion of the AWG Number of Stranded Wire to the Metric System with Strand Cross-Section and Number of Wires .....	183
8.7.3. Conversion of Metric and Anglo-American Measurements .....	185
8.8 Tension on Copper Wires.....	187
8.9 Increase in Tensile Force due to Deversion (Belt Friction).....	189