
TABLE OF CONTENT

CHARACTERISATION OF DAMAGE PHENOMENA OF STONE AND RELATED BUILDING MATERIALS (PLASTER, RENDERING, MORTAR ETC.)

R. Snethlage	
Risk Number: Documentation and Objective Assessment of Environmental Damage to Marble and Sandstone Sculpture	35
R. Bugini, L. Folli	
New marbles for the Italian architecture (1920–40)	41
K. Ekinci, A. Karagöl, G. G. Küçükosmanoğlu, I. Polat Pekmezci	
Characterization and deterioration of materials of Rumelifeneri Fortress in Istanbul	47
A. Kück, Ch. Pötzl, R. López-Doncel, R. Dohrmann, S. Siegesmund	
Tuffs in pre-Columbian and colonial architecture of Oaxaca, Mexico	53
J. Diaz, B. Menéndez	
Sustainable lime restoration mortars: Physical properties and durability assessment	59
C. Noël, B. Menéndez	
Comparison of physico-chemical properties between ancient and restoration renders in the Vexin Français area (NW of Paris)	65
S. Ahmadinezhad, A. Sansonetti, A. Pane, D. Biondelli	
Study of decay patterns and damage assessment of the Achaemenian rock-reliefs of Naqsh-e Rustam	71

E. Vasanelli, A. Calia, G. Quarta, D. Melica, M. Masieri, A. Monte, F. Micelli Effect of fire on the durability of a porous calcarenite: the case study of a tobacco factory in Tricase (Lecce, Southern Italy)	77
M. Drdácký, D. Frankeová, Z. Sližková Variations of characteristics of sandstone subjected to weathering and conservation interventions	83
N. Freudenberg, T. Frühwirt, K.-J. Kohl, M. Kutz, H. Siedel, J. Wichert Thermal behavior of building sandstone: laboratory heating experiments vs. real fire exposure	89
L. Schröer, T. De Kock, N. Boon, V. Cnudde Exploring microbial communities inhabiting gypsum crusts of weathered natural building stones	95
M. Haselberger, M. Milchin, K. Fuchs, G. Enkhbat, Ts. Tsolmon, J. Weber, G. Krist Stone Cultural Heritage in Mongolia – Model-like Study and Condition Assessment of the Site of Ikh Khöshööt	101
M. Morales Demarco, E. Cocorel Characterization and deterioration assessment of Kösseine Granite in Palacio Salvo, Montevideo, Uruguay	107
A. Eckart, R. Sobott, H. Kletti, T. Burkert, W. Jäger 2000 years of use of plaster as building and restoration material for the „Takht-e Soleyman“ in Western Azerbaijan, Iran	113
A. Kück, Ch. Pötzl, R. López-Doncel, R. Dohrmann, S. Siegesmund Effects of zeolites and swellable clay minerals on water-related properties and thermal dilatation in volcanic tuff rocks	119
M. Saba, J. Lizarazo-Marriaga, N. L. Hernandez-Romero, C. Tedeschi, E. Quiñones-Bolaños Physico-chemical characterization of the Cartagena Wall and quarry material stone used for its restoration	125
Á. Török, L. Germinario, R. López-Doncel, Ch. Pötzl, S. Siegesmund Comparative analysis of volcanic tuffs from Europe, Asia and North-America	131
W. Wedekind, E. Harutyunyan, S. Siegesmund The Cathedral-ruins of Zvartnots and Avan (Armenia) – a comparative study on decay and restoration	137

L. Sousa, J. Menningen, S. Siegesmund
Notes of a bowing behavior on limestone 145

L. Lazzarini, E. Tesser
**The four sculpted columns of the St. Mark basilica' ciborium, Venice:
marbles, polychromy, past treatments** 151

METHODS FOR THE INVESTIGATION OF STONE DECAY; IN-SITU AND NON-DESTRUCTIVE TESTING

R. Livingston, C. Grissom, Y. Gorokhovich
**Portable XRF study of the geographic distribution and growth rate of
mn-rich rock varnish** 161

B. Sacchi, E. Cantisani, T. Salvatici, C. A. Garzonio
**Microdrilling resistance measurements system and mortar penetrometer:
two methods for evaluating in situ mortar resistance** 167

Ma H., Dai Sh., Zhou Y., Qian B., Tang Zh., Zhang G., Xiang J., Zhen G.
**Ultrasonic testing of the dolomite marble statue of Soong Ching-ling
with respect to the depth of cracks and deterioration state** 173

T. Waragai, T. Takemura
Acoustic emission behavior of rocks subjected to temperature changes 179

St. Pirskawetz, J. Menningen, S. Siegesmund
**Acoustic emissions – insights into the decay mechanisms of thermally
treated marbles** 185

D. Benavente, M. de Jongh, J.J. Galiana-Merino, C. Pla, J. Martinez-Martinez,
M. Lee, M. E. Young
**Automatic estimation of the P- and S-wave onset-times in weathered
sandstones by salt crystallisation** 191

H. Yang, D. W. Kim, C. H. Lee, J. H. Yoo
**A study on nondestructive diagnosis and conservation scheme of
Korean dinosaur egg fossil sites in Hwaseong Gojeongri** 197

H. Y. Park, S. Y. Park, C. H. Lee, J. H. Park
**Material Characteristics and Non-Destructive Diagnosis of Stone Standing
Buddha and Stone Chamber of Mireukri Temple Site in Chungju, Korea** 203

Ch. Pötzl, A. D. Öcal, T. Cramer, S. Siegesmund	
Decay of Pre-Columbian phallic stone monoliths	209
St. Pfefferkorn, Ch. Franzen	
Evaluation of effective compression strength of natural stone by drilling resistance measurements	215
L. Germinario, C. T. Oguchi	
Historical man-made caves in Japan: Vulnerability of rocks and cultural assets in the underground environment	221
F. Dursun	
Material Characterization And Decay Of The Limestones Used In Historical Structures Of Mardin, Turkey	227
M. Drdácký, M. Eisler, R. Krompholz	
In-situ investigation of stone consolidation effects with immersed ultrasonic double-probe	233
F. Tiefensee, C. Degel, P. Weber, W. Bost, M. Moses, M. Schmieger	
A new system for fast ultrasound-tomography at marble sculptures	239
D. M. Freire-Lista, L. Sousa	
Fuente de Cibeles of Madrid and decay of Montesclaros marble	245
O. Sánchez Rovira, D. Giovannacci, J.-D. Mertz, J. Wassermann, B. Ledésert, R. Hébert, Y. Mélinge	
Water content estimation using non-destructive tools applied to archaeological materials	251
W. Wedekind, E. Harutyunyan, N. Novakovic, S. Siegesmund	
Experimental conservation and first investigations on the weathering of Geghard Monastery (Armenia)	257
W. Wedekind, Ch. Schmidt	
The three funerary Stelae Project	263
C. Tedeschi, M. Taccia	
Monitoring and evaluation of damaging of traditional cleaning techniques of stones with 3D optical microscopy profilometry	269
M. Deprez, G. De Schutter, V. Cnudde, T. De Kock	
Freeze-thaw weathering: Digging deeper in the temperature and length evolution of natural stones	275

G. Cardani	
The evaluation of the masonry quality in historical load-bearing stonework	281
P. Kozub	
Karsten Tube Penetration Test – new findings and new evaluation method	287
S. T. Park, S. H. Kim, C. H. Lee	
Evaluation on Reusability and Damage of Stone Properties for Repair of Wolnamsaji Temple Site Stone pagoda for Gangjin Korea	293

LONG-TERM MONITORING OF STONE MONUMENTS AND BUILDINGS

S. Hamilton, C. Graham, Ch. Gerdwilker, J. Hepher, S. Mirashrafi, E. Hyslop	
Challenges of investigating decay in an enclosed bedrock monument: Fossil Grove, Glasgow	303
O. E. Gilbert, L. Mol, O. Campbell, T. Blenkinsop	
The Influence of Angle of Ballistic Impact on Stone Weathering	309
J. H. Park, C. H. Lee, Y. H. Jo	
A Study on Conservation Management System of Fortress Cultural Heritage by Behavior Monitoring and GIS	315
S. H. Kim, C. H. Lee	
Change of Environmental Stability by Improved Airtightness in the Korean Ancient Royal Tombs from the 6th Century Baekje Kingdom	321
A. G. Costa	
Long-Term Monitoring Of Processes Affecting Stone Materials Applied To Historical And Contemporary Buildings In Brazil	327
J. Menningen, S. Siegesmund, R. Krompholz, Y. Rieffel	
Comparative, Non-destructive analysis of the marble sculptures General von Bülow and von Scharnhorst in Berlin	333
O. A. Cuzman, S. Rescic, P. Tiano	
A new portable technique to evaluate the compatibility of protective treatments applied on monumental stones	339
S. Laue, C. Schaab, D. Drese, D. Krauthäuser, G. Helfmeier, J. Vogt	
Long-Term investigations and monitoring of the salt loaded Crypt of St. Maria im Kapitol, Cologne	345

K. Wilhelm, D. Gulotta, A. Leslie, M. Krus, V. Thome, R. Kilian, H. Viles Reviving 'Asterixe': a unique long-term archive for built heritage research	351
S. Siegesmund, M. Morales Demarco, R. Wittenbecher, M. Pfeifer, K.-J. Stein Koelga Marble as building veneer at the Town Hall of Wermelskirchen (Germany): Weathering dynamics, bowing potential and risk assessment:	
Part I	357
S. Siegesmund, M. Morales Demarco, R. Wittenbecher, M. Pfeifer, K.-J. Stein Koelga Marble as building veneer at the Town Hall of Wermelskirchen (Germany): Weathering dynamics, bowing potential and risk assessment:	
Part II	363
A. Bordi, M. Matteini, F. Piqué 2-step DAP consolidation of marble busts on the facade of Lugano's Cathedral	369
I. Kisilewicz The Impact of Natural Climate Hazards impact on the Restoration of Dragomirna Church	375
J. M. Quadrizius, E. Wendler, J. Meinhardt Improved Evaluation of Karsten Water Uptake Measurements: Visualisation of the Soaking Front by Absorption of Dye Solutions	381
Y. Praticò, F. Girardet, R. J. Flatt New insights on the causes of contour scaling in Swiss sandstones	385

SIMULATION AND MODELLING OF DECAY

Xiaolin C. Performance Simulation of Solid Brick Construction under the Impacts of Increased Precipitation as a Consequence of Climate Change	395
F. Dursun, T. Topal Effect of weathering tests on microfracture properties of the massive and vesicular basalts	401
Mengjun J., Ling H. The implication from the Na₂SO₄ Crystallization behaviors on Dafosi sandstones during salt-loaded hygrothermal aging cycles	407

J. Bartholdy, P. Klenz Larsen, J. Bredal-Jørgensen The damaging effect of “eco-friendly” deicing salts on building materials	413
A. Stahlbuhk, M. Steiger Investigations on the Supersaturation and Damage Potential of Nitrate Salts Relevant for Objects of Cultural Heritage	419
E. Huby, C. Thomachot-Schneider, P. Vázquez, G. Fronteau, J. Menningen, S. Siegesmund Dilatation behavior of building stones repaired with a restoration mortar	425
J. Frick, N. Sakiyama, B. Hejazi, F. Lehmann, S. Gambarelli, J. Ožbolt, H. Garrecht Real time monitoring of moisture and salt transport and related modelling	431
M. Michette, H. Viles, C. Vlachou, I. Angus Modelling the effect of repointing and galletting on moisture dynamics in historic masonry at the Wardrobe Tower, Tower of London	437
D. Zhiyan, S. Wakiya, Y. Kohdzuma Deterioration Mechanism of Japanese Sandstone During the Drying and Wetting Cycles	443
C. Blaeuer, B. Rousset, A. Loeffel, P. Voelkle, H. Haeberli Tests on repair mortars for sandstones at Berne Cathedral	449
E. Mizutani, D. Ogura, M. Abuku, H. Derluyn Preliminary investigation of change of pore structure due to salt precipitation during evaporation in brick with X-ray computed tomography	455
M. García-González, M. A. Soto-Zamora, R. A. López-Doncel The behavior of the Cantera Hermosa tuff to the process of salt crystallization, using water with different levels of pollution – Preliminary results	461
E. Wendler, S. Endemann, G. Klapprott Stress-strain-adapted Involvement of Cross-iron in Soft Sandstone Material	467
Y. Wang, Sh. Yang, Z. Yu, Q. Guo, H. Viles Evaluation of the impact of salts on the deterioration of a sandstone rock-hewn cave-temple in NW China through the combination of in situ salt extraction and salt behaviour modelling	473

TECHNOLOGY AND DEVELOPMENT OF IMPROVED TREATMENTS AND USE OF STONE IN NEW BUILDINGS

C. Franzen, H. Ettl, G. Grassegger, F. Grüner, R. Lenz, H. Siedel, E. Wendler	
Desalination of porous building material by means of poultices, the new revised WTA-Guideline	483
I. Rörig-Dalgaard, A. E. Charola	
A new method for evaluating the condition of fired clay bricks: Preliminary results	489
J. Otero, A. E. Charola	
Reflections on Nanolime Consolidation	495
T. Wangler, A. M. Aguilar Sanchez	
Potential damage mechanism in Swiss molasse	501
J. Orlowsky, F. Braun	
Comparison of different evaluation methods concerning water absorption	507
E. Mascha, J. Weber	
Assessment of the Spatial Distribution of Consolidating Solids in the Pore Space by SEM	513
B. Sena da Fonseca, A. P. Ferreira Pinto, S. Piçarra, A. Rodrigues, M. F. Montemor	
Comparative behavior of commercial and laboratory-developed alkoxysilane-based products as consolidants for carbonate stones	519
E. Mascha, M. Ban, A. Rohatsch, J. Weber	
Silicates for the Consolidation of Stone: Nano Silica vs. Ethyl Silicate	525
E. Sassoni, E. Franzoni, S. Siegesmund, G. W. Scherer	
10 years of marble conservation by ammonium phosphate: laboratory and field data on protection, consolidation and mitigation of bowing	531
J. Engel	
Development of a New Cleaning Product for Heavy Metals Containing Facades	537
L. Masson, J.-S. Guédon, J.-D. Mertz, E. Keita, M. Duc, A. Bourgès	
Swelling inhibitors for clay materials: Comparison of industrial and natural surfactants	543
N. M. E. Stucchi, E. Tesser, A. Benedetti, F. Antonelli, G. Zaccariello	
Experimental silica nanoparticles products for the consolidation of silicate stones	549

J. Menningen, E. Sassoni, S. Siegesmund Marble bowing: Prevention by the application of Hydroxyapatite – a systematic study	555
M. Cicardi, C. Corti, O. Salvadori, F. Piqué Endolithic microorganisms in carbonatic rocks and conservations problems	561
G. Sikorowski, F. Piqué, M. Matteini, Y. Praticò Planar Abrasion Meter	567
A.-L. M. Hoyt, H. Cölfen Stone pore imitating artificial test systems: Current prototypes and potential for cultural heritage care	573
A. Suzuki, C. Riminesi, B. Salvadori, S. Vettori, M. Ricci, L. Bartoli, A. Zanini Graphic vandalism: preliminary cleaning tests on stone materials by (Yb:YAG) active fiber laser system	579
L. M. Ottosen A short review on electro-desalination and its application for chlorides and nitrates	585
C. L. Nunes, K. Mlsnová, J. Válek Limewashes with linseed oil: effect on the moisture transport of natural stone	591
S. Rucker, C. Pötzl, E. Wendler, R. Dohrmann, R. López-Doncel, S. Siegesmund Improved consolidation of volcanic tuff rocks with TEOS	597
M. Teipel, Ch. Pötzl, W. Wedekind, B. Middendorf, S. Siegesmund Approach on developing stone replacement mortars for the cultural heritage of Armenia	603
V. Vergès-Belmin, L. Leroux, J. Hénin, S. Duchêne Stone conservation issues after the 2019 fire at Notre-Dame cathedral	609

ASSESSMENT OF LONG-TERM EFFECTS OF TREATMENTS

A. Thorn Two case studies on the usefulness of surface water absorption as a meaningful property of sandstone	621
---	-----

A. Kieferle	
Conservation of a Recent Conservation Based on Silicic-Acid-Ether and Silica Sol	627
F. Braun, J. Orlowsky	
Single-Sided NMR Experiments on Hydrophobic and Long-Term	
Weathered Natural Stones	633
L. Normand, D. Giovannacci, V. Vergès Belmin, St. Duchêne, J. Hénin	
Terahertz time-domain imaging (THz-TDI):	
A new non-destructive method for the determination of consolidation depth on stone	639
M. Milchin, C. Pesce, J. Weber, G. Krist, M. Ban, M. Anghelone	
An Evaluation of Shelter Coats for the Protection of Outdoor Stones	645
T. Meier, M. Auras, R. Sobott, C. Leonhardt, J. Heller, H. Drengemann,	
D. Köhn, T. Steinkraus, Y. Esel, S. Hintz, E. Erkul, D. Schulte-Kortnack	
Investigating Surficial Alterations of Natural Stone, Bricks, and Plaster	
by Ultrasonic Surface Measurements	651
T. Schade, B. Middendorf	
Microstructural investigations regarding the recrystallization process of	
gypsum based mortars for historic exterior masonry	657
D. Odgers, N. Cox	
Wells Cathedral, West Front sculpture – detailed assessment of	
conservation repair techniques	663
K. Fuchs, F. Pintér	
Performance of lime-based sacrificial layers for the conservation of	
porous limestone in an urban environment: a case study	669
M. Groh, F. Braun, J. Orlowsky	
Contact angle measurements on hydrophobic natural stones	675
R. Manganelli Del Fà, B. Sacchi, A. Sansonetti, S. Vettori, C. Riminesi,	
F. Fratini, S. Lugli, G. Tirelli, G. Grassi, M. Laurenzi Tabasso	
Hydration-Dehydration decay on sandstone: Possible remedy and evaluation	
of the effects of a specific anti-swelling product	681
B. T. Gemedo, L. Fusade, H. Viles	
Efficacy of traditional conservation methods for the protection of	
rock-hewn heritage sites: Lessons from Lalibela, Ethiopia	687

T. Ishizaki, N. Araki

Evaluation Of The Deterioration Of A Stone Gate (Torii) And Its Protective Measure 693

Jinhua W., Shu J., Shibing D.

A Brief Analysis of the Conservation Status and Prospect of Grotto Temples in China 699

IMPACT OF CLIMATE CHANGE ON STONE DECAY OF CULTURAL HERITAGE

S. Siegesmund, St. Pirskawetz, F. Weise, R. Plagge, Y. Rieffel

Winter Shelters For Marble Sculptures Of The Schlossbrücke Berlin:

Climatic Constraints 709

D. McCaughey, I. Simpson, E. Hyslop, C. Graham, A. Turmel

Baselining Sandstone Heritage for Conservation in a Climate Change(d) Future 717

Yiding W., Shibing D.

Challenges of Conservation of Sand-stone Architectural Heritage

in Tsada Basin of Ngari Prefecture, Tibet, China 723

D. Guilbert, St. Caluwaerts, K. Calle, N. Van Den Bossche, V. Cnudde, T. De Kock

The urban heat island impact on frost weathering of natural building stones

in Ghent, Belgium 729

L. Mertens, C. Sabatzki

Suevite, a Rare Impact Stone: Research and Development of Conservation Materials 735

S. Laratte, C. Thomachot-Schneider, G. Fronteau, A. Guillaneuf, P. Vazquez

Salt sensitivity of the stones of the Porte de Mars of Rheims caused by

the impact of an acid atmosphere exposure 741

J. Meinhardt, K. Schmeikal

Investigations of aversive conditioning of biogenous growth on exposed

sandstone objects 747

A. Nielsen, M. Brancucci

Characterisation of pollutant deposits: possible relationships between

areas of origin and degradation of marble monuments. 753

P. Brimblecombe

Future Climate and Stone Decay 759

O. Bilal, N. Rozgonyi-Boissinot	
Diagnosis of Stone Deterioration in Crac des Chevaliers	765
K. Sterflinger, A. Rohatsch, L. Belanyecz, A. Huber	
Live and let die? Biofilms on Stone: Possibilities, Limits and Risks of Combating	771
D. Badreddine, K. Beck, X. Brunetaud, A. Chaaba, M. Al-Mukhtar	
Stone-mortar compatibility:	
Thermo-hygric cycling induced aging of masonries polluted by salt	777
Shibing D., Jizhong H., Jinhua W., Hongsong L.	
Stone Conservation in China – with Focusing on Carbonate Stone	
Conservation Practice	783

REPORTS ABOUT STONE CONSERVATION: CASE STUDIES AND PROJECTS

T. Dettmering, Z. Liu, Y. Tang, Y. Wang, S. Dai	
Preliminary study on lime mortars used for stone masonry of the Great Wall	
built by Ming Dynasty in China	793
Š. Govže, S. Dolenc, A. Pondelak	
Consolidation Of The Bioclastic Limestone Using Three Different	
Carbonate-Forming Consolidants: In Situ Study	799
M. Stuff, K. Rübner, C. Prinz, N. Rische, M. Chronz, H.-C. Kühne	
Towards a better understanding of tuff stone deterioration	805
G. H. Lee, C. H. Lee, J. H. Park	
Material Characteristics and Provenance Presumption for Stone Properties	
of the Korean Ancient Tomb in Seoul Songpa District	811
N. Maklada, Y. Saad, Y. Schaffer, P. Gendelman, Y. Sha'altiel, E. Greenfeld, I. Rosental	
The Crusader Wall of Caesarea Resurrected: A Conservation Stonework Project	817
D. Kowalik-Kociszewska	
Examination of Historical Sandstone Epitaphs as a Searching For a	
New Method of Conservation	823
V. Marinković, D. Mudronja, S. Dolenc, A. Pondelak	
Case study: Stone Consolidation of Reliefs inside the Cathedral of St. Lawrence,	
Trogir – Results and Doubts of Field Treatment	829

L. Mol, C. Brassey, L. Clarke, O. Gilbert, O. Campbell, T. Blenkinsop Heritage in the Crossfire	835
M. Avrahami, J. Neguer The conservation of the Lintels of the Church of the St. Sepulchre	841
B. Brunet-Imbault, Ph. Bromblet, H. de La Boisse, B. Reidiboym, C. Guinamard Conservation of delaminated stone: Diagnosis and tests for the restoration of the medieval church of Sainte-Croix de Celleneuve (Montpellier, France)	847
S. Godts, C. De Clercq Analysis of the Salt Content during Water Bath Desalination of a Polychrome Limestone Relief	853
J. De Roy, S. Huysmans, L. Fontaine, C. De Clercq, S. Godts A pilot study to define the restoration for 68 sandstone sculptures of the Calvary of the St. Paul's Church in Antwerp (Belgium)	859
E. Steindlberger Conservation of northern Hessian tuffstones – A building material used for the monuments in the Bergpark Wilhelmshöhe	865
R. Will, K. Lange Restoration of the 172 facade sculptures of the New Palace, Potsdam – development and transfer of an economic concept	871
J. Meinhardt, J. Gutglück, K. Schmeikal, G. Hauff Exemplary conservation of the polychromy on the Gothic sandstone sculptures of the Halberstadt cathedral using facing-technology	877
K. Lange, R. Will The marble sculpture collection in front of the palace of the New Chambers, Potsdam Outlining current research and practice in sculpture restoration	883
E. İpekci, R. Aydin, M. Taykurt Daday, H. Yüceer, H. Böke Weathering of Limestone at Anavarza Archaeological Site in Turkey	889
A. Logreira, L. Ashon Conservation of the Cloisters at Norwich Cathedral, UK	895
A. Sobhi, H. Marey Mahmoud, A. Brania The burial tombs of Tell-Basta: the building materials and restoration attempt	901

M. Uggeri, E. Concina, A. Sansonetti, R. Bugini Study of the lithotypes used in the mosaics of artificial grottoes and nymphaea in Lombardy	907
S. Fujii, K. Kiriyama, S. Wakiya, T. Koezuka, Y. Kohdzuma Influence of heat and moisture environment inside the shelter on sodium and calcium sulfate behavior	913
F. Grüner, J. Zöldföldi Natural stone exchange and quality assurance in the case of the Ulm Minster in Baden-Württemberg	919
Ch. Burris The Discovery, Analysis and Replication of a Blue Romanesque Revival Stopping Mortar	925
E. Stadlbauer, G. D'ham, A. Ehling, R. Niemeyer, C. Reulecke, A. Rinne, F. Schlüter, B. Skasa-Lindermeir Preservation and conservation of Goslar slate – The example of the Mönchehaus in the world heritage historic city of Goslar, Germany	931
J. Zöldföldi, L. Holzkamp, R. Lenz, A. L. Krautheimer, F. Grüner On-site tests to assess wet vacuum cleaning technology for salt reduction on sandstones	937
M. Auras, O. Hahn, C. Germann-Janssen, K. Keller, K. Petersen, B. Skasa-Lindermeir, E. Wendler Moisture, salt and mould – conservation problems in a medieval Mikveh	943
T. Pinkale, K. Bommes, P. Kozub Drachenfels Trachyte – Research into the preservation of Cologne Cathedral's medieval radiating chapels	949
A. Steyer, M. Steyer, M. Auras, E. Riemer Possibilities and limitations of the computed tomography as a non-destructive testing tool using a Jupitercolumn as an example	955
E. van Plehwe-Leisen, H. Leisen, A. Pranz Stone Conservation in Bagan, Myanmar, and Training of Conservation Professionals	961

DIGITALIZATION AND DOCUMENTATION IN STONE CONSERVATION

M. Rahrig, A. Karl, P. Bellendorf Evaluation of conservation measures for historical stone surfaces by using Opto-Technical Monitoring	971
C. Franzen, S. Fuchs, A.-H. Hamdan, K. Hiemann, P. Katranuschkov, K. Luig, D. Mustedanagic, R. Schülbe, M. Seeaed, R. Scherer BIM-SIS Adaptive Knowledge Based System for Identification of Stone Damages in Building Information Modeling Working Environment	977
E. Valero, F. Bosché, A. Forster, I. M'Beirick, L. Wilson, A. Turmel, E. Hyslop Development of a novel open tool for the segmentation of 3D point clouds of masonry walls	981
G. Siedler, S. Vetter, J. Kaminsky Data acquisition, management and evaluation for stone conservation projects with digital mapping	987
O. Campbell, T. Blenkinsop, O. Gilbert, L. Mol, T. Lik Lee Microstructural Damage from Bullet Impacts in Heritage Sandstones	993
St. Duchêne, J.-L. Bodnar, K. Mouhoubi, D. Giovannacci Stimulated infrared thermography (SIRT) revealing the hidden decoration of the Vierge du trumeau in Reims Cathedral	999
B. Kozub, P. Kozub 3D-structured light scanning technology in the field of cultural heritage	1005
J. Menning, T. Fetzer, A. Schäfer, G. Reis, S. Siegesmund Ultrasound tomography and 3D scanning Technologies as a tool to constrain the weathering state of objects made of marble	1011
Young H. J., Chan H. L. Development and Application of Three-dimensional Digital Technology for Stone Heritage Conservation	1019
K. Bommes, T. Pinkale, P. Kozub St Walburga – Local value of polychrome terracotta figure results in conservation intervention and 3D-Scan generated replacement	1025
A. Sturm, B. Edelstein, C. Snyder Lifting Mountains: The Treatment of a 7th Century Cambodian Sandstone Krishna Sculpture	1031

OPEN TOPICS

M. I. Borges	
Exposure of Rosa Arronches and Santa Eulália Granites to Aggressive Environments: Ice-Deicing and Acidic Solutions – Analysis of Performance	1041
T. De Kock	
Perceptions of stone. Some examples from the historical use of Lede stone, Belgium	1047
S. Raneri, T. De Kock, A. Rohatsch, M. Ban	
The Potential of Neutron Imaging in Stone Conservation	1053
M. Snethlage	
The interdisciplinary "Arbeitsgruppe Steinkonservierung der DDR" – a historical study on their scientific work (1972–90)	1059
M. Schidlowski, F. Ruegenberg, T. Bader, A. Diekamp	
A Study for Assessing the Relationship between Calcination Temperature and Mineralogical Composition of Natural Hydraulic Limes (NHL)	1065
T. Bader, J. Gagl, A. Diekamp	
DOLOMIA: A survey on the historic and present-day use of dolomite rock as building material in Tyrol, Austria	1071
J. Kaminska, Ch. Fuchs, J. Meinhardt	
Cleaning of discoloured objects made of low-fired gypsum	1077
H. Simonsson	
The implementation and use of standards as a means to meet climate change challenges	1083
V. Pelin, B. Ratoi, B. Apavaloei, V. Vasilache, I. Sandu, M. Branzila	
Conservation State Assessment of the Golia Monastery Enclosure Wall	1089
Z. Hering	
Related research of the loss compensation of the volcanic tuffs	1095
Ch. Abitz, A. Richter, F. Klebe	
Excavating and Preservation of Dinosaur Tracksites in Obernkirchen Sandstone	1101
F. Schad	
Cleaning Monuments: From Brooms to Numerical Simulation	1107

A. Ehling	
Global heritage Stone Resource (GHSR) – an initiative of the IUGS	1113

EXCURSION

S. Siegesmund, F. Wiese, J. Lepper, J.-K. Stein	
Naturwerksteine in Göttingen und Umland	1121
Stadttxkursion Göttingen	1142
R. Snethlage, B. Lammerer	
Siegfried Siegesmund on his 65th birthday – A Laudation	1201
List of Authors	1217